



Mr. Handyman of South Essex County Highlights Considerations for Entry Doors in Beverly

October 13, 2026

PEABODY, MA - October 13, 2026 -

The front door of a home takes on more than most homeowners give it credit for. It gets opened and shut thousands of times a year, holds back wind driven off the harbor, keeps conditioned air where it belongs, and stands as the first thing a visitor notices from the sidewalk. Mr. Handyman of South Essex County points out that when homeowners start thinking about replacing entry doors in Beverly, the decision usually involves more than picking a color and a style, and understanding the trade-offs ahead of time tends to lead to better results.

Climate is the starting point. Coastal communities along the North Shore deal with salt-laden air, wind-driven rain, heavy snow loads, and the freeze-thaw cycles that come with a New England winter. Those conditions are hard on materials. Solid wood doors suit many older homes in neighborhoods such as Ryal Side and Beverly Cove. Wood expands and contracts with humidity and requires regular refinishing, particularly in areas exposed to afternoon sun or ocean winds.

Fiberglass has become a common alternative because it resists swelling, holds paint or a wood-grain finish well, and does not dent the way steel can. Steel doors bring strength and a lower price point, though

scratches and dings near the coast can rust if the finish is not maintained. Mr. Handyman of South Essex County notes that the right choice often comes down to the amount of shelter the entry has. A door tucked under a deep covered porch faces very different weather than one exposed on a flat facade.

Energy loss is another consideration worth examining before a purchase. Older entries in Beverly frequently leak air not because the door slab has failed but because the weatherstripping has hardened, the threshold has settled, or the frame itself has shifted over the decades. Checking for daylight around the perimeter on a bright day, or feeling for drafts along the hinge side during a cold snap, gives a rough sense of how much air is moving through.

In some cases, new weatherstripping and an adjustable threshold solve most of the problem for a fraction of the cost of replacement. When a full replacement makes sense, energy performance ratings, the number of glass panes, and the quality of the frame seal typically matter more for comfort than the door material itself.

Water management deserves attention as well, and it is the piece most often overlooked. Rot in the framing beneath a threshold is common in older housing stock and is rarely visible until the existing unit is removed. It ranks among the more frequent surprises turned up when entry doors in Beverly are pulled from openings that have sat through decades of coastal weather.

Mr. Handyman of South Essex County advises homeowners to plan for the possibility that a replacement project uncovers soft sheathing or a damaged sill. A properly sloped sill, a sill pan beneath the unit, and proper flashing at the head of the opening are what keep water from entering the wall cavity. Skipping those details tends to shorten the life of an otherwise good door.

Security is a related but separate question. The strength of an entry has less to do with the door slab than with what surrounds it. Short screws in a strike plate, a hollow jamb with no blocking behind it, or hinges secured only to trim create weak points regardless of how heavy the door feels. Longer screws that reach the framing, reinforced strike plates, and a deadbolt with adequate throw address most of that. Glass placement matters too, since sidelights or panels within arm's reach of the lock change how the entry should be secured.

Fit and function round out the list. Older homes in Beverly often have openings that are out of square or sized differently than modern standards, which means a stock door may need modification or a custom order. Swing direction affects how a small entry hall functions. Threshold height matters for anyone using a walker or wheelchair. Storm doors can trap heat against a dark-colored slab and, in some cases, affect warranty coverage. Historic district guidelines may apply to certain properties, and confirming that early avoids complications later.

Choosing the right entry door involves more than comparing materials or styles. The condition of the frame,

weather exposure, energy efficiency, water protection, security, and proper fit all influence how well the door performs over time. Mr. Handyman of South Essex County notes that homeowners evaluating entry doors in Beverly should consider the entire opening and surrounding structure before deciding whether repair or full replacement is the most appropriate approach.

About Mr. Handyman of South Essex County:

Mr. Handyman is your one-call solution for a wide range of home maintenance and repair needs. Our uniformed technicians are fully insured professionals. We arrive on time, in uniform, and in a marked van with the tools to complete the job right.

Mr. Handyman technicians are highly skilled craftsmen with an average of 10 years? experience in the trades. We?re home repair and improvement experts, and we are known for the quality of our workmanship and professional reliability, so you know the job will be done correctly and efficiently.

###

For more information about Mr. Handyman of South Essex County, contact the company here:Mr. Handyman of South Essex CountySteve Moradsteve.morad@mrhandyman.com179 Lake St, Peabody, MA 01960

Mr. Handyman of South Essex County

Mr. Handyman is your one-call solution for a wide range of home maintenance and repair needs.

Website:

https://www.mrhandyman.com/south-essex-county/?cid=LSTL_MHM000197&utm_source=gmb&utm_campaign=local&utm_medium=organic

Email: steve.morad@mrhandyman.com

