



## **Extreme Auto Service Launches Advanced Diagnostics in Utah**

*October 14, 2026*

CENTERVILLE, UT - October 14, 2026 -

Extreme Auto Service has completed the facility-wide implementation of advanced computerized diagnostic platforms to expand and modernize its Utah auto repair services. Completed following a phased four-month rollout that began in June, the technical upgrade equips all primary service bays with Bosch ADS 625X diagnostic stations and Autel MaxiSYS Ultra intelligent diagnostic tablets. The new hardware directly addresses the rising complexity of modern vehicle platforms by providing technicians with high-speed serial data bus analysis, component topology mapping, and integrated original equipment manufacturer (OEM) technical service bulletins.

Automotive designs across consumer and commercial sectors increasingly rely on distributed Controller Area Networks (CAN), Controller Area Network Flexible Data-Rate (CAN-FD), and Diagnostics over Internet Protocol (DoIP). These electronic architectures link dozens of microprocessors governing safety-critical subsystems, including anti-lock braking, electronic throttle management, adaptive cruise control, active lane-keeping assistance, and advanced driver assistance systems (ADAS). When communication faults, voltage irregularities, or sensor degradations occur, standard code-reading scanners often fail to isolate root causes, resulting in protracted manual circuit testing and extended vehicle downtime that disrupts daily

transportation.

The newly installed diagnostic systems combine multi-channel digital storage oscilloscopes, signal waveform generators, and cloud-linked repair validation software. By capturing live telemetry and comparing dynamic sensor signals against manufacturer-specified operating tolerances, technicians can evaluate component performance without invasive component teardowns. During a 60-day operational review encompassing 310 customer and fleet vehicles prior to full deployment, the shop recorded a 65 percent reduction in preliminary scanning times, cutting average intake testing from 46 minutes to under 16 minutes per vehicle. Complex electrical fault isolation times dropped from an average of 3.2 hours to 1.1 hours, overall repair turnaround times decreased by 24 percent, and first-time diagnostic accuracy increased from 87 percent to 96 percent across domestic, European, and Asian vehicles.

"Vehicle electrical systems have become intricate digital ecosystems where a single degraded sensor or wiring harness fault can trigger cascading error codes across unrelated control modules," said Christian Sheffield, founder and chief executive officer of Extreme Auto Service. "Standardizing our diagnostic bays on high-speed scanning hardware and bidirectional control tools provides technicians with real-time signal testing and circuit mapping directly at the vehicle. This operational shift removes ambiguity, accelerates troubleshooting, and ensures that electrical and mechanical issues are accurately repaired during the initial shop visit."

In conjunction with the hardware installation, all service technicians completed 40 hours of certified factory training covering high-voltage hybrid safety protocols, communication bus diagnostics, battery management system evaluations, and dynamic radar-camera recalibration procedures. Extreme Auto Service has also upgraded its customer documentation process. Vehicle owners and commercial fleet managers now receive comprehensive digital diagnostic summaries featuring freeze-frame fault data, live sensor readouts, thermal anomaly logs, and prioritized component recommendations prior to authorizing any repair work. A complementary technical guide explaining sensor network maintenance, diagnostic trouble codes, and vehicle network health has also been published on the company website to help motorists interpret modern error alerts.

By aligning independent service capabilities with factory-level specifications, the investment prepares the independent facility to manage passenger vehicles, hybrid drivetrains, and light-duty commercial fleet transports under strict manufacturer guidelines. Extreme Auto Service continues to incorporate objective technical standards and transparent digital reporting across its Utah auto repair services to support long-term vehicle reliability, road safety, and operational efficiency for local drivers.

###

For more information about Extreme Auto Service, contact the company here: Extreme Auto Service  
Extreme Auto Service 801-516-4711 extremeauto@gmail.com 606 N. 1000 W. Centerville, UT 84014

### **Extreme Auto Service**

Website: <https://www.extremeautogroup.com/>

Email: extremeauto@gmail.com

Phone: 801-516-4711

