



## **Mold Removal Express Shares Key Signs of Winter Attic Mold Issues**

*February 24, 2026*

FORT COLLINS, CO - February 24, 2026 - PRESSADVANTAGE -

Mold Removal Express, a family-operated mold remediation company serving the Denver metropolitan area, has published comprehensive guidance identifying warning signs that indicate homeowners may need professional attic mold removal during the winter months. The resource aims to help Colorado property owners recognize early indicators of mold development before contamination becomes extensive.

The newly released guidance addresses a growing concern among homeowners as colder temperatures create potentially high humidity conditions that can accelerate mold development in attic spaces. Winter months present unique challenges for attic environments, where temperature differentials between heated living spaces and cold exterior roofing materials often lead to condensation accumulation on structural surfaces. This moisture provides the primary requirement for mold colonization in otherwise dry building materials. Simply stated, it's like running a giant science experiment in your attic.

According to the company, several indicators warrant immediate attention from property owners. Visible discoloration on attic sheathing, particularly dark staining on plywood or oriented strand board near roof peaks and valleys, often signals active mold colonization. Musty odors detected when entering attic spaces,

even when no visible growth is apparent, may indicate hidden contamination behind insulation or in areas with limited visibility. Peeling paint on ceilings directly below attic areas can also suggest elevated moisture conditions overhead.

"Winter creates specific conditions that homeowners should monitor carefully," said Richard Jones, owner of Mold Removal Express." Addressing these issues early can prevent more extensive remediation work and protect both the structural integrity of the home and the health of its occupants."

The company emphasizes that inadequate attic ventilation frequently contributes to winter mold problems. When warm, moist air from living spaces rises into attic areas through gaps around light fixtures, plumbing penetrations, or poorly sealed access hatches, the resulting condensation provides moisture (and associated humidity) necessary for mold establishment. Bathroom exhaust fans that terminate in attic spaces rather than venting to the exterior represent another common contributor to winter moisture accumulation. Ice dam formation along roof edges can also force moisture beneath shingles and into attic cavities, creating secondary contamination pathways that may go undetected until significant growth has occurred.

Homeowners who observe frost accumulation on the underside of roof decking during cold weather should consider this a significant warning indicator. While frost itself does not constitute mold growth, its presence confirms that moisture levels within the attic exceed safe parameters and will likely support fungal development once temperatures moderate in spring months.

Mold Removal Express uses a proprietary sterilizing fog treatment technology, an approach that allows treatment of all exposed and contaminated attic spaces and surfaces without requiring demolition of structural materials or removal of insulation. This methodology enables the company to address mold growth in difficult-to-access areas where traditional removal techniques may prove impractical or cost-prohibitive. The treatment penetrates into corners, crevices, and porous materials where conventional surface cleaning cannot reach.

For property owners who proceed with remediation, Mold Removal Express offers post-treatment airborne mold testing as an additional service. These live spore culture tests verify that the sterilizing fog treatment has successfully eliminated mold contamination, providing documentation that the attic environment has been restored to safe conditions.

Mold Removal Express has provided mold remediation services throughout the Denver, Fort Collins, and Boulder areas for over a decade. The company specializes in treating mold contamination in attics and crawlspaces, backing completed work with a money-back guarantee. Additional information about identifying

winter attic mold conditions is available through the company website.

###

For more information about Mold Removal Express, contact the company here: Mold Removal Express Richard Jones (720) 443-4222 Info@MoldRemovalExpress.com 410 Jefferson St Fort Collins CO 80524

## **Mold Removal Express**

*Fast, effective & 100% guaranteed mold removal across Northern Colorado! Mold Removal Express eliminates hazards in 24 hrs. Backed by a full money-back guarantee. Call now to make black mold removal simple, safe, and stress-free.*

Website: <https://www.moldremovalexpress.com/>

Email: [Info@MoldRemovalExpress.com](mailto:Info@MoldRemovalExpress.com)

Phone: (720) 443-4222

