



SafeAir Certified Mold Inspection Inc Releases New Guidance on Mold Risks Following Water Damage

July 10, 2026

July 10, 2026 -

SafeAir Certified Mold Inspection Inc has published a new educational resource, "Mold After Water Damage: How Fast It Grows and What to Do in the First 48 Hours," which explains how quickly mold can develop after water damage and outlines the steps property owners can take during the critical period following a water-related event. The guidance was released this month through the company's blog to help homeowners better understand the timeline of mold growth and the importance of a prompt response.

According to the newly published resource, mold growth can begin within 24 to 48 hours after moisture reaches porous building materials such as drywall, wood, carpet, and insulation. The article notes that mold spores are already present in indoor environments and can begin colonizing damp surfaces when moisture remains trapped after leaks, plumbing failures, or other water-related incidents.

"Mold problems often start much sooner than many people realize," said Alex Laldin, Marketing Director for SafeAir Certified Mold Inspection Inc. "The information in this guide is intended to help property owners

understand the timeline involved and why early action after water damage can make a significant difference."

The company's guidance explains that the first two days after a water event are critical. During that time, moisture can penetrate building materials and create conditions that support mold growth if drying efforts are delayed. The article states that the extent of resulting damage often depends on how quickly affected areas are identified and dried.

The resource also highlights common causes of indoor water damage. While severe storms can contribute to moisture problems, the article notes that plumbing failures, appliance line leaks, and slow, hidden leaks are frequently responsible for mold-related concerns inside homes. These issues may go unnoticed for extended periods, allowing moisture to remain present long enough for mold colonies to develop.

In addition to explaining the timeline of mold development, the guidance describes the environmental factors that influence growth. Temperature, moisture levels, and the type of material affected can all impact how quickly mold becomes established. The article emphasizes that porous materials are particularly vulnerable because they can retain moisture below the surface even when the visible area appears dry.

SafeAir's publication also addresses the role of airborne mold spores. The company explains that mold spores enter buildings through doors, windows, ventilation systems, and everyday activities. Under normal conditions, these spores remain inactive, but prolonged moisture can create conditions that allow them to grow and spread.

The educational resource was developed as part of the company's ongoing effort to provide information about mold-related conditions in residential properties. By focusing on the period immediately following water damage, the guide aims to help readers recognize situations that may require closer inspection and moisture assessment before visible mold becomes apparent.

Industry sources referenced in the article indicate that mold growth is often associated with materials that remain wet for extended periods. The guidance notes that early drying and moisture control remain among the most important factors in reducing the likelihood of widespread contamination following a water intrusion event.

The company states that the publication is intended to support informed decision-making following water-related incidents and to encourage prompt evaluation of areas affected by leaks, appliance failures, or other moisture sources. The resource is available through the SafeAir Certified Mold Inspection Inc website as part of the company's educational content library.

SafeAir Certified Mold Inspection Inc provides mold inspection and testing services and publishes educational

information related to indoor environmental conditions. Through its website, the company shares articles covering mold growth, moisture issues, and inspection topics intended to help property owners better understand potential concerns within residential buildings.

###

For more information about SafeAir Certified Mold Inspection Inc, contact the company here: SafeAir Certified Mold Inspection Inc Jeremy Shelton 4046950673 inspection@safeairtesting.com 2210 Defoor Hills Rd NW, Atlanta, GA 30318, United States

SafeAir Certified Mold Inspection Inc

SafeAir Certified Mold Inspection Inc provides professional mold inspections, testing, and indoor air quality services. We're committed to accurate results, fast service, and protecting your home or business from hidden mold and air quality issues.

Website: <https://safeairmoldtesting.com/>

Email: inspection@safeairtesting.com

Phone: 4046950673

