Gateway Restoration Uncovers Weeks of Hidden Water Damage Behind a Chandler Kitchen Cabinet

October 29, 2026

October 29, 2026 -
Gateway Restoration recently completed a water damage restoration project in Chandler, Arizona, where a single faint stain near a kitchen cabinet turned out to be the only visible sign of a slow leak that had been soaking structural materials for weeks. The case highlights how hidden moisture can cause substantial damage long before a homeowner notices anything obvious.

The incident involved a slow leak inside the wall behind a sink cabinet. With no standing water and no dramatic burst, the moisture had quietly saturated the studs, bottom plate, and block wall over an extended period. The team used moisture meters to trace the water outward from the sink cabinet, identifying the wet boundary before any materials were disturbed. This measured approach allowed the crew to set containment and open only the affected section of wall rather than removing sound finishes unnecessarily.

From there, the certified technicians performed behind the wall water damage restoration after a hidden kitchen leak in Chandler, following IICRC S500 standards throughout the process. Air movers and dehumidifiers were positioned to dry the exposed cavity, corroded supply lines and stained studs were removed, and the block wall was treated to guard against mold, which can develop on damp materials within 24 to 48 hours. The job concluded with the cavity clean, dry, and ready for reconstruction.

Danjee Moser, speaking for Gateway Restoration, noted that hidden leaks often reveal themselves in small ways. "A recurring stain, soft drywall, or a faint musty smell can be the only clues that moisture is spreading behind a finished surface," Moser said. "Our role is to find the full extent of the damage, not just the part that is visible, so the repair addresses the actual source rather than the symptom."

The project reflects the type of diagnostic work that defines water damage restoration Chandler AZ homeowners frequently require after appliance and plumbing leaks. Kitchens are a common site for this kind of slow damage, since refrigerator supply lines, dishwasher connections, and sink plumbing can leak for

weeks behind cabinetry. Gateway Restoration provides kitchen water damage restoration services in Chandler that combine moisture mapping, controlled demolition, structural drying, and insurance documentation into a single coordinated process.

Moser added that early detection makes a meaningful difference in outcomes. "The difference between a drying job and a full cabinet replacement often comes down to how quickly the moisture is traced and contained," Moser said. "Careful hidden kitchen leak detection Phoenix and Chandler residents can rely on helps keep a minor repair from becoming a major one."

Gateway Restoration encourages any homeowner who notices a mystery stain, warped flooring, or an unexplained odor near the kitchen to schedule an inspection before the problem spreads further.

Gateway Restoration is a family-owned company serving Chandler, Phoenix, and surrounding Arizona communities since 2016. The licensed and IICRC-certified team specializes in water damage restoration, fire and smoke restoration, mold remediation, and related construction services, and assists homeowners with documentation throughout the insurance claims process.

###

For more information about Gateway Restoration, contact the company here:Gateway RestorationDanjee Moser(480) 990-4142service@gwraz.com2301 S. Stearman Dr. #4 Chandler, AZ 85286

Gateway Restoration

Gateway Restoration has served Chandler, AZ for 9+ years, specializing in water, fire & mold restoration. Our licensed, IICRC-certified team provides 24/7 emergency services, restoring property, peace of mind & minimizing disaster heartache.

Website: https://gatewayrestoration.com/

Email: service@gwraz.com

Phone: (480) 990-4142