Go To Guy Home Services: Atlanta Flood Alert Puts Decks in Focus

October 23, 2026

ATLANTA, GA - October 23, 2026 -
An October 10, 2026, flash flood warning for central Fulton County and other parts of metro Atlanta has brought attention to what heavy rain can leave beneath a residential deck. The National Weather Service reported that radar indicated one to three inches of rain had fallen in the warned area when it issued the alert, with additional rainfall possible. The warning named Atlanta among the locations at risk of flash flooding; it did not identify damage at any particular home or deck.

The archived National Weather Service warning covered several counties in and around the city. Small streams, urban areas and poorly drained sites were among the places of concern. A countywide alert describes a hazard, not the condition of each yard. Once it is safe to access a property, the useful question for an owner of an elevated deck is whether water or moving soil changed the support system, stairs or connection to the house.

A wet deck surface does not answer that question. Rain may pass through board gaps and drain away without affecting the underlying structure. Water that collects near posts or carries soil away from a landing presents a different situation. The distinction depends on the site, the path of the water and the condition of the materials and connections. Neither the storm's name nor the type of decking on the surface can settle it.

The National Weather Service advises people to avoid floodwater, obey closures and wait for an all-clear before entering flood-damaged structures. Those precautions come before any deck check. After access is safe, photographs from firm ground can document a changed stair landing, displaced soil beside a support, an unusually loose guard or a visible change where the deck meets the house. A photograph is a record of what can be seen, not a structural finding. If the deck has shifted or a connection appears compromised, it should not be loaded until an appropriately qualified professional evaluates it.

The North American Deck and Railing Association's deck evaluation guide treats stairs, footings and

supports, beams and joists, the ledger connection, surface boards and guards as separate inspection areas. That framework matters after intense rain because the most visible part of a deck may not be the part in question. A board that needs attention is different from a stair attachment that has moved or a post whose surrounding ground has washed away. Each observation calls for a finding about the component and its cause before anyone chooses a repair or replacement.

Go To Guy Home Services' Atlanta deck installation page describes deck design, framing, foundations, rebuilds and replacements. The work is relevant to a choice between leaving a sound structure alone, correcting an identifiable component and rebuilding when the condition warrants it. The October alert supplies a reason to examine a particular property's drainage and deck connections, not a basis for assuming that a rebuild is necessary.

A useful assessment would distinguish a drainage problem outside the deck from a change in a structural component. It would also avoid treating every discoloration as flood damage or every dry-looking surface as proof that the framing is sound. Previous plans and dated photographs, where available, can help show whether a stair, guard or connection changed after the rain. Where floodwater remains, electrical equipment is affected or entry has not been cleared, local authorities and appropriately qualified specialists take priority over a deck evaluation.

The warning has expired, but its location-specific record remains relevant to the homeowners it covered. It offers a reason to look at actual site conditions rather than assume that a regional storm damaged every deck in its path. Some properties may need no work; others may warrant a closer examination of supports or connections. The decision follows evidence at the property, not the warning alone.

###

For more information about Go To Guy Home Services, contact the company here:Go To Guy Home ServicesKelly Crow+14702605221kelly@gotoguyatl.com1257 Poplar Grove Dr NE, Atlanta, GA 30306, United States

Go To Guy Home Services

Go To Guy Home Services is an Atlanta-based custom deck builder and outdoor living specialist serving homeowners across the Metro Atlanta area.

Website: https://www.gotoguyatl.com/

Email: kelly@gotoguyatl.com

Phone: +14702605221

